



Honeywell | Fire Safety



FS-TOOLS 3.02.008

Training Series

What's New In This Release

Honeywell

OVERVIEW / FEATURE SUMMARY

This document provides expanded discussion of the enhancements in FS-Tools 3.02.008

- **SS Detector Support.** Added support for New System Sensor detectors.
- **Defects and bug fixes.**
 - FS-Tools crashes when performing a System Status Upload from an Evolution panel.
 - FS-Tools does NOT allow the Module "Supervisory" Type ID selection in ES-50/200 databases.
 - Special Zones "CO Active Zone" is inaccessible in FS-Tools Non-Canadian customer databases.
 - FS-Tools becomes unresponsive for ES-1000 History or Walktest Uploads.
 - FS-Tools "Edit Devices" causes Photo/CO and Fire/CO detector Zone settings to turn OFF when included with other detector types.
 - ANN-I/O (Loop 1) Detector displays multiple Point selections in FS-Tools ES-1000 database.
 - Unable to select ANN-I/O (Secondary ANN-Bus) Zone 110-149 in FS-Tools ES-1000 database.

OVERVIEW / FEATURE SUMMARY

This document provides expanded discussion of the enhancements in FS-Tools 3.02.005

CLSS Connectivity. Users can now login to CLSS From within FS-Tools.

CLSS Database backup. Users can now backup programming databases to CLSS Site Manager

- **CLSS Connected Central Station report.** Users can now generate a CLSS Central Station report from within FS-Tools.
- **CLSS Pathway Pro Communicator.** Users can now configure new onboard Pathway Pro Communicator.
- **ES-1000 Support.** Users can now configure New 954 point Fire Alarm Control Unit.